




10/040512

COPY

I hereby certify that this correspondence is being deposited with the United States Postal Service on the date set forth below as First Class Mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

Date of Deposit November 12, 2004


George E. Haas, Reg. No. 27,642

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant:	Kurt A. Reichold, <i>et al.</i>	Art Unit:	1746
Patent No.:	6,792,637 <i>B2</i>	Examiner:	Frankie L. Stinson
Issue Date:	September 21, 2004		
Serial No.:	10/040,512		
Filed:	January 8, 2002		
For:	Automatic Detergent Dispensing System for a Warewasher		
			Certificate NOV 23 2004 of Correction

REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 C.F.R. §1.322

Commissioner For Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

Applicants respectfully request that a Certificate of Correction be issued pursuant to 37 C.F.R. §322 to rectify a typographical error in the patent. The error is listed below and on the attached PTO-1050 form.

In column 5, line 35, after "alarm flag had" insert -- been previously set by a previous finding of unchanged conductivity. If the alarm flag --.


This line of text was erroneously omitted from the issued Letters Patent but appears in the original specification filed on January 8, 2002. The error is considered of consequence, as the meaning of the sentence is unclear without correction. Therefore, issuance of a Certificate of Correction is requested.

NOV 23 2004

Because this error occurred during printing of the patent, a fee is not required for the Certificate of Correction. However any fee that is due should be charged to Deposit Account No. 17-0055 .

Respectfully submitted,
Kurt A. Reichold

Dated: November 12, 2004

By: 
George E. Haas
Registration No. 27,642

Quarles & Brady LLP
411 E. Wisconsin Avenue
Milwaukee, WI 53202-4497
(414) 277-5751

QBMKE5658999.1

NOV 23 2004

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,792,637 B2

DATED : September 21, 2004

INVENTOR(S) : Kurt A. Reichold, et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 5, line 35, after "alarm flag had" insert --been previously set by a previous finding of unchanged conductivity. If the alarm flag --.

MAILING ADDRESS OF SENDER: George E. Haas
Quarles & Brady LLP
411 East Wisconsin Ave.
Milwaukee, WI 53202

PATENT NO. 6,792,637

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office; U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

Doc. No. 5659002.1

NOV 23 2004